



**Technical Service
BULLETIN**

June 14, 2002

Title:

CD PLAYER GRINDING NOISE

Models:

'03 Matrix

T S B

AUDIO
AU003-02

Introduction A new CD player mechanism has been developed to correct a possible grinding noise from the CD player during vehicle deceleration.

- Applicable Vehicles**
- **2003** model year **Matrix** vehicles equipped with the **single disc CD player** built before the VIN shown below.
 - Radio faceplate **model numbers** affected are **AD1800** and **AD6808**.

Production Change Information

MODEL	STARTING VIN
Matrix	2T1KR32E73C028364

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
86120-02330	Same	Radio with CD Player	1
86120-02340	Same	Radio with CD and Cassette Player	1

Repair Procedure Order a replacement radio through the Delphi exchange program (AER) by calling 1-800-321-6970.

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
860031	R & R Radio Tuner Assembly	0.3	86120-02330 86120-02340	91	99

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

